

Table №2:												
75mV Shunts (Amperes)	Weight (Kg)	Dimensions (mm)										
		L	B	H	A	A1	E	h	A2			
75	0.19	120	22		105		60	6				
100	0.25	130	30		110		60	6				
150	0.29	130	22		110		60	12				
200	0.38	130	30		110		60	12				
300	0.54	130	30		110		60	18				
500	1.10	180	35	20	130		40	14				
750	1.50	180	50	20	130		40	14				
1000	2.00	180	70	20	130		40	14				
1500	2.8	180	100	20	130	50	40	14				
2000	3.50	200	85	50	145	50	40	15				
3000	4.4	200	105	50	145	50	40	15				
4000	7	240	120	70	175	50	40	20				
5000	11	240	160	70	175	50	40	20				
6000	11	240	160	70	175	50	40	20				
7500	13	240	210	70	175	50	40	20	60			

Table №3:												
75mV Shunts (Amperes)	Clips								Potential clips			
	Screws		Nuts		Lock-nus		Washers		Screws		Spring washers	
	size	q-ty, pcs	size	q-ty,	size	q-ty,	size	q-ty,	size	q-ty,	size	q-ty,
75	M6 x 20	2	M6	2	M 6	2	6	4	M5 x 10	2	5	2
100	M 8 x 22	2	M8	2	M 8	2	8	4	M5 x 10	2	5	2
150	M 8 x 28	2	M8	2	M 8	2	8	4	M5 x 10	2	5	2
200	M 8 x 28	2	M8	2	M 8	2	8	4	M5 x 10	2	5	2
300	M10 x 45	2	M10	2	M10	2	10	4	M5 x 10	2	5	2
500	M16 x 55	2	M16	2	M16	2	16	4	M5 x 10	2	5	2
750	M16 x 55	2	M16	2	M16	2	16	4	M5 x 10	2	5	2
1000	M16 x 55	2	M16	2	M16	2	16	4	M5 x 10	2	5	2
1500	M16 x 55	4	M16	4	M16	4	16	8	M5 x 10	2	5	2
2000	M16 x 60	4	M16	4	M16	4	16	8	M5 x 10	4	5	4
3000	M16 x 65	4	M16	4	M16	4	16	8	M5 x 10	4	5	4
4000	M18 x 80	4	M18	4	M18	4	18	8	M5 x 10	4	5	4
5000	M18 x 80	6	M18	6	M18	6	18	12	M5 x 10	4	5	4
6000	M18 x 90	6	M18	6	M18	6	18	12	M5 x 10	4	5	4
7500	M18 x 90	8	M18	8	M5 x 10	8	18	16	M5 x 10	4	5	4

Table №4:			
75mV Shunts (Amperes)	Wire cross-section (mm ²)	Dimensions of manganin plates (width x thickness) mm	Number of plates on every side
15	15	-	-
100	25	-	-
150		22 x 1.5	1
200		30 x 1.5	1
300		30 x 2.5	1
500		35 x 6.0	1
750		50 x 7.0	1
1000		60 x 7.0	1
1500		50 x 7.0	2
2000		50 x 5.0	4
3000		50 x 5.0	8
4000		50 x 8.0	8
5000		50 x 7.0	12
6000		50 x 8.0	12
7500		50 x 8.0	18

